

## Compatibility with Windows 11

### Devices and software

The following devices and software from Dürr Dental are compatible with the operating system Windows 11.

#### Intraoral camera systems

| Product              | REF                                                                          |
|----------------------|------------------------------------------------------------------------------|
| VistaCam iX          | 2108-120-50                                                                  |
| VistaCam iX HD Smart | 2109120050, 2109120051,<br>2109120052, 2109120055,<br>2109120056, 2109120057 |

#### Image plate scanner and small X-ray system

| Product                 | REF                                                                    |
|-------------------------|------------------------------------------------------------------------|
| VistaScan Mini View 2.0 | 2144100800, 2144100805                                                 |
| VistaScan Mini Easy 2.0 | 2144100500, 2144100505                                                 |
| VistaScan Mini View     | 2142-000-80, 2142-000-81,<br>2142-000-82, 2142-000-83                  |
| VistaScan Mini Easy     | 2143-000-50, 2143-000-53,<br>2143-000-54, 2143-000-60,<br>2143-000-61  |
| VistaScan Mini Plus     | 2141-000-80, 2141-000-81,<br>2141-000-83                               |
| VistaScan Mini          | 2141-000-50, 2141-000-52                                               |
| VistaScan Ultra View    | 2170100500                                                             |
| VistaScan Nano Easy     | 2160100500                                                             |
| VistaScan Combi View    | 2151-000-80, 2151-000-85                                               |
| VistaScan Omni View     | 2151-000-82                                                            |
| VistaScan Pano View     | 2151-000-81                                                            |
| VistaScan Combi Plus    | 2150-000-50, 2150-000-52,<br>2150-000-53, 2150-000-57,<br>2150-000-58, |
| VistaScan Plus Ceph     | 2150-000-50                                                            |
| VistaScan Plus Omni     | 2150-000-52                                                            |
| VistaScan Perio Plus    | 2140-000-80                                                            |
| VistaScan Perio Net     | 2140-000-70                                                            |
| VistaScan Perio         | 2140-000-50, 2140-000-51,<br>2140-000-52, 2140-000-53                  |
| VistaRay 7              | 2121-130-62, 2121-130-63                                               |

#### X-ray unit

| Product              | REF                                                               |
|----------------------|-------------------------------------------------------------------|
| VistaPano S          | 2207-000-50                                                       |
| VistaPano S Ceph     | 2207100014                                                        |
| VistaPano S 2.0      | 2208100004                                                        |
| VistaPano S Ceph 2.0 | 2208100005                                                        |
| VistaVox S           | 2210200001<br>(Replacement of the frame<br>grabber card required) |
| VistaVox S (2nd Gen) | 2210200653                                                        |
| VistaVox S Ceph      | 2210200575                                                        |

#### Software

| Product           |                         |
|-------------------|-------------------------|
| VistaSoft         | Version 3.0.1 or higher |
| VistaSoft Monitor |                         |



We recommend updating the software regularly.